

Name..... Group..... Mark.....

**8.20 - Ferrous Hound: Dip Coating**

Step 1	
	Metal is clean and has no sharp edges
Step 2	
	Heated using blow torch or oven
Step 3	
	Remove from heat/oven using tongs and gloves
Step 4	
	Dip into fluidising bath
Step 5	
	Cooling for 5min and trimming off excess